


AnyTone D578UV Mobile Radio Base Band Update Instruction

**UNINSTALL AND REMOVE ALL OLD VERSIONS OF THE SCT_PORT.EXE
PROGRAM BEFORE DOING THIS UPDATE – ONLY USE THE LATEST
INSTALL PROGRAM**

1. Press and Hold both the PUSH key (Channel Knob Push) and MENU key, and
TURN ON THE RADIO and the screen will show  “WARNING Boot
Mode for Sct!!!” SetupSCT_PORT.msi

2. Use the USB cable to connect radio and your PC

3. Run the **most current SetupSCT Port. msi**


The file is provided in this update in the Install Base Band folder

IMPORTANT NOTE

**If an error message appears indicting you need to install Net Framework 2.0
you will have to use the following link to install Net Framework 3.5 which is
the update that will have the needed install files to continue:**



<https://www.microsoft.com/en-US/download/details.aspx?id=21>

4. Run SCT_PORT Host Controller by Double Clicking on the Icon on your Desktop.





AnyTone D578UV Mobile Radio Base Band Update Instruction




5. Follow the screen guides below to set the SCT_Port Host Controller to update the Base Band:





AnyTone D578UV Mobile Radio Base Band Update Instruction



AnyTone D578UV Mobile Radio Base Band Update Instruction



AnyTone D578UV Mobile Radio Base Band Update Instruction



The update is now complete.

Unplug Radio Power Source to reboot radio.

Reapply Power and Turn Radio back on.