

BridgeCom Maverick Bluetooth updating

To upgrade the BridgeCom Maverick Bluetooth (BT), you need to install the **OTA V1.7.2.apk** on your Android phone, or you can source **JL OTA Up-grade** from the Apple Store and install it on your iPhone.

1. Program = the **OTA V1.7.2.apk (Android)** or **JL OTA (Apple Store)**
 - a. This is the update program for the radio BT Firmware (FW).
The update file for the radio is with a .ufw extension.
2. The OTA program will automatically source for the .ufw file saved in the phone

How to check BT version?

On the radio open the MENU and SETTINGS and look under DEVICE INFO for the Bluetooth Software Version.



Upgrade BT to latest version on the Maverick radio


1. Connect your Android phone to your computer via a cable.
2. Swipe top-down and allow the Android phone to accept file transfer
3. Open the Android phone folder on the computer and locate the Download folder from your phone – then drag and drop the Maverick BT files you received to the phone DOWNLOADS folder – files **OTA V1.7.2.apk**, and **ET25_QXDZ_V1024.ufw**



4. On your phone, locate the FILES or FILE DOCUMENTS or similar folder and open it and look for the DOWNLOADS folder where you placed the programs

5. Find and install **OTA V1.7.2.apk** on your Android phone.

If you use iPhone, you can source **JL OTA Upgrade** in Apple store and install the APP on your phone directly.



6. Open the OTA program you just installed on your phone. Make sure your Maverick radio has the Bluetooth function turned on and set it in a “pairing” mode. On the phone, click the bottom left Bluetooth icon so that the phone scan for nearby Bluetooth devices. You will see the following – select the ET25SE_BLE_XXXXX result (which is your radio).



7. The phone will display a blue progress bar when doing the bluetooth firmware upgrading. You can check the bluetooth firmware version in radio menu when the progress bar finishes.